

Transboundary Spill NPDES CA0108928 Order No. R9-2014-0009, Amended by R9-2014-0094

Type ☐ A ☒ B

(CAL OES 1-800-852-7550)

Name of Person Reporting Spill Steven Smullen

Telephone No. of Person Reporting 619-662-7601

Spill Location/Name Tijuana River at the International Boundary

GPS Coordinates 32.32.30 N, 117.2.18 W

Spill Reached: ☐ Drainage Channel ☐ Drainage Structure ☒ Surface Water

Spill Reached: ☐ MS4 MS4 Owner _____

Vol Spill to MS4 _____ Vol Recovered from MS4 _____

Estimate Spill Volume from All Sources 0.143 million gallons (MG)

Volume That Reached: Surface Water, Drainage Channel, Not Recovered from MS4 0.143 MG

Total Recovered Volume 0

Number of Spill Appearance Points 1

Appearance Descriptions Slightly cloudy water

Spill Flow: Start Date 04/24/17 Start Time 1215

Notification: Date 04/24/17 Time 1220

Operator Arrival: Date 04/24/17 Time 1230

Spill Flow: End Date 04/24/17 End Time 1235

Cleanup Completed: Date N/A Time _____

Probable Cause of Spill Power failure at CILA PS

Notification of CAL OES Date 04/25/17 Time 0900

CAL OES Control Number 17-3026 Blake Tyson

Description of Spill Flow Destination Tijuana River Channel

Spill Flow Cause Power failure at PS CILA

Spill Flow Failure Point CILA Pump Station

Spill Flow Storm Event ☐ N/A

Spill Corrective Actions Power restored at 1235 04/24/17

Spill Flow Response Actions None

Spill Flow Completion Date 04/24/17

Investigation ☐ N/A Reasons _____ Completion Date _____

Health Warnings Posted ☐ Yes ☒ No

Name of Beaches Impacted: ☐ None ☐ Surface Water Impacted: Tijuana River

Location and No. Of Samples Collected (Type A) N/A Number _____

Parameters Tested N/A

Regulatory Agencies Receiving Results N/A

Methodology for Spill Volume Estimate Calculated from 15 min gage data USIBWC gage

Amount of Spill Recovered None

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Certifying Official Steven Smullen Title Area Operations Manager Date 4/25/17

Signature (b) (6)

Spill Apr 24, 2017

Tijuana River

Date	Time	Gage Height (m)	Flow (CMS)	Flow (MG)
4/24/2017	12:45	11.958	0	0.00000
4/24/2017	12:30	11.977	0.25	0.05944
4/24/2017	12:15	11.984	0.35	0.08321
4/24/2017	12:00	11.939	0	0.00000

Flow	0.14265 MG
------	------------

Not for Public Distribution